



GARY R. HERBERT  
Governor  
SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Minerals Inspection Report

Reviewed *JSB*

Report Date: **04/06/2016**

Mine Name: Fox Canyon	Permit Number: S/49/0080	Mine Status: Active
Operator Name: Beck and Beck Construction	Inspection Date: 04/05/2016	Permit Fees: Paid
Inspector(s): A. Abate	Inspection Time: 3:00 PM	Bond Amount: \$60,500
Attendee(s):	Weather: Clear 50s	Bond Escalation: 01/01/2019
Inspection Purpose: Follow up from enforcement		Prior Inspection: 1/12/2016

### Conclusions and Recommendations

Cessation Order MC-2016-60-01 was issued on 1/14/2016 for expanding beyond the 5-acre small mine permit boundary. The abatement required the operator to reclaim at least 7 acres of the operation in order to continue to qualify for a small mine permit. The abatement also required the operator post a reclamation bond for \$60,500 for the current 12 acres of disturbance. The operator is currently in the process of reclaiming the area and has posted the required reclamation bond. MC-2016-60-01 is recommended for termination.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
The small mine permit is for a 5-acre mine site. The Division reviewed the areas that have been reclaimed. The surrounding area is comprised of new residential subdivisions, or subdivisions in the process of being constructed. Fox Canyon further to the east remains undeveloped for now. The permit area is serving as a construction equipment staging area and rock crushing operation to service the construction activity in the vicinity.		
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i>	<input type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Heavy equipment, trucks, trailers associated with rock crushing operations were present onsite. No deleterious materials appeared to be stored on-site in a hazardous manner.		
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Some reclamation work appears to have been undertaken on the northern side of the permit area. The operator is in the process of grading the land to make way for a residential subdivision.		
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i>	<input type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i>	<input type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i>	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: *[Signature]*

CC:

File: /nrwogms1/OGM/GROUPS/MINERALS/WP/M049-Utah/S0490080-FoxCanyon/inspections/Insp-04052016.pdf



### Fox Canyon Mine S/49/0080



Disturbance footprint January 2016





Reclamation activities to date as of April 2016